

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERTL. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

#### OLENE S. WALKER Governor

GAYLE F. McKEACHNIE Lieutenant Governor

Representatives Present During the Inspection:				
Company	Rusty Netz Environmental Coordinator			
OGM	Karl Houskeeper Environmental Scientist III			

# **Inspection Report**

Permit Number:	C0070042		
Inspection Type:	PARTIAL		
Inspection Date:	Wednesday, July 21, 2004		
Start Date/Time:	7/21/2004 8:00:00 AM		
End Date/Time:	7/21/2004 10:00:00 AM		
Last Inspection:	Monday, June 14, 2004		

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, ~Temp 87 Deg F InspectionID Report Number: 339

Accepted by: pgrubaug

7/28/2004

Permitee: SUNNYSIDE COGENERATION ASSOCIATES Operator: SUNNYSIDE COGENERATION ASSOCIATES

Site: STAR POINT REFUSE

Address: PO BOX 159, SUNNYSIDE UT 84539

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

**Current Acreages** 

Min	eral	Owne	ership
-----	------	------	--------

#### **Types of Operations**

152.81 Total Permitted	☐ Federal	Underground
88.78 Total Disturbed	☐ State	Surface
Phase I	☐ County	Loadout
Phase II	<b>✓</b> Fee	Processing
Phase III	☐ Other	<b>✓</b> Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

The permittee submitted an application to the Division on July 6, 2004, for removal/adjustment of culverts along the North side of the permit area. The application was assigned Task ID #1983 and is currently under review by the Division.

Inspector's Signature

Karl Houskeeper, Environmental Scientist III

Date

Wednesday, July 21, 2004

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070042 Inspection Type: PARTIAL

Inspection Date: Wednesday, July 21, 2004

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
  For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
  Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	<b>✓</b>		✓	
2.	Signs and Markers	✓		<b>Y</b>	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	<b>✓</b>		<b>Y</b>	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	<b>V</b>			
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring		<b>~</b>		
4.e	Hydrologic Balance: Effluent Limitations	<b>~</b>			
5.	Explosives		<b>V</b>		
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	<b>✓</b>			
8.	Noncoal Waste	<b>~</b>			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.	a Roads: Construction, Maintenance, Surfacing				
16.	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

**Inspection Continuation Sheet** 

Permit Number: C0070042 Inspection Type: PARTIAL

Inspection Date: Wednesday, July 21, 2004

Page 3 of 3

## 1. Permits, Change, Transfer, Renewal, Sale

The permitted submitted an application to the Division on July 6, 2004, for removal/adjustment of culverts along the North side of the permit area. The application was assigned Task ID #1983 and is currently under review by the Division.

### 2. Signs and Markers

The mine ID sign is located at the contact point of the public road to the permit area and on the West entrance to the permit area (by the reclaimed #1 Mine access road). The signs contain all of the appropriate information.

All other signs and markers observed during the inspection were in compliance with the approved MRP.

## 4.a Hydrologic Balance: Diversions

The diversions on the property have been cleaned and are in compliance with the designs in the approved MRP.